

8869 Protocol

Continue push the key "LIGHT/IR" to activate USB Function,
And push the key continuously to disable USB function

USB data transfer:

FF FF XX XX XX XX XX XX XX XX XX XX XX XX AA

Start EMS IRH IRL TKH TKL MAXH MAXL MINH MINL DIFH DIFL AVGH

AVGL sign end

Sign :

1st: 0: C 1 :F

2nd: 0: TK valid, 1: TK OVER